

Guangzhou Hong Modi Auto Parts Co., Ltd

Ignition Coils & Spark Plugs - Reference List

151 references | WhatsApp +86 135 3142 1489 | autoparts@hongmodi.com | www.hongmodiautoparts.com
Reference numbers are quoted for identification purposes only.

- 1. IHI spark plugs A2760901480 and A2760901580 for the left and right sides of the Mercedes-Benz M276DE30AL engine (C250, E250, C400, SL400, ML400 3.0L).**
OE: A2760901480, A2760901580, M276DE30AL
- 2. Bosch Ignition Coil F01R00A134**
OE: F01R00A134
- 3. Chery E3f10 1.5T Ignition Coil ? E3f103705110 / F01r00A110**
OE: E3F103705110, F01R00A110
- 4. Ignition Coil F01R00A041/F01r00A093 ? Compatible with Chery A3, Guanzhi, Kaiyi, and Riich (4G13/4G16 Engines)**
OE: F01R00A041/F01R00A093, 4G13/4G16
- 5. OEM F01R00A024 Q21-3705110 Ignition Coil**
OE: F01R00A024, Q21-3705110
- 6. Automotive Ignition Coil ? Compatible with Chery QQ 1.0L (2012?2018 Models) and QQ3 (2011?2014 Models) ? Part Number F01R00A023**
OE: F01R00A023
- 7. Bosch Ignition Coil #F000ZS0103 ? Brand New, Genuine Original**
OE: F000ZS0103
- 8. Ignition Coil 01R43059X01 S113705110JA 101R42076X01 ? Suitable for Chery**
OE: 01R43059X01, S113705110JA, 101R42076X01
- 9. 01r4304r01 Ignition Coil for Marshall Motorola**
OE: 01R4304R01
- 10. OEM Ignition Coils MR994643, MR994642, and FK0279 for Mitsubishi Eclipse, Galant, and Lancer**
OE: MR994643, MR994642, FK0279
- 11. High-Performance Ignition Coil Pack 476q-4D-3705800 for Byd F3 & Hafei Saima**
OE: 476Q-4D-3705800
- 12. Ignition Coil F01R00A065 / F01R00A106 ? Compatible with BYD F3, G5, G6, S6, S7, Qin, Han, Song, and Tang Models**
OE: F01R00A065, F01R00A106
- 13. Ignition Coil F01R00A062 483QB3705100**
OE: F01R00A062, 483QB3705100
- 14. OEM F01r00A011 Ignition Coil for BYD F6/G3/M6/L3/S6/G6 and Haima**
OE: F01R00A011, F6/G3/M6/L3/S6/G6
- 15. High-Quality Original Ignition Coil F01r00A048 488QA3705100 ? Compatible with BYD M6/S6 2.4L**
OE: F01R00A048, 488QA3705100
- 16. Ignition Coil Set ? Compatible with BYD F3/Qin/G3/L3/T3 (2005?2019, 2011?2017); Replaces FK044412305 and 473QE3705100.**
OE: F3/QIN/G3/L3/T3, FK044412305, 473QE3705100
- 17. Ignition Coil OE 473qb-3705100 473qb3705100 Ib53705100 Fk0398**
OE: 473QB-3705100, 473QB3705100, IB53705100, FK0398
- 18. Ignition Coil OEM KRKTT15 371QA-3705100 371QA3705100 F01R10A139 ? Compatible with BYD F0, Geely Panda, and Chery**
OE: 371QA-3705100, 371QA3705100, F01R10A139
- 19. Ford 1L2Z-12029-AA Ignition Coil Assembly**
OE: 1L2Z-12029-AA
- 20. 1F2U-12029-AC for Ford Mondeo 1F2Z-12029-AC DG485 GY07-18-100 1Pc Ignition Coil**
OE: 1F2U-12029-AC, 1F2Z-12029-AC, GY07-18-100
- 21. 1 Ignition Coil (Part No. 27301-37100) ? Compatible with Hyundai Sonata, Kia Optima, and Optima 2.5L/2.7L Models**
OE: 27301-37100, 2.5L/2.7L
- 22. 1 Ignition Coil (Part No. 27301-37100) ? Compatible with Hyundai Sonata, Kia Optima, and Optima 2.5L/2.7L Models**
OE: 27301-37100, 2.5L/2.7L
- 23. 27301-26002 Uf133 88921361 ignition coil suitable for models such as the Hyundai Accent**
OE: 27301-26002, 88921361
- 24. Ignition coil KKA1434 27301 23720 2730123720 27301-23900 2730123900**
OE: KKA1434, 2730123720, 27301-23900, 2730123900
- 25. All-new Hyundai-Kia direct ignition coils 27301-23700 (27301-23710)**
OE: 27301-23700, 27301-23710
- 26. Genuine 2730123400 Hyundai Sonata/Kia Carens Clarus ignition coil**
OE: 2730123400
- 27. Ignition coil for Hyundai Coupe Elantra Lantra II Sonata 27301-23003 27301-23003**

OE: 27301-23003

28. Ignition coils 27301-22600 C1350 suitable for Dodge Verna and Hyundai Accent 1.5L and 1.6L L4 engines.

OE: 27301-22600

29. Ignition coils 27301-22040 and 27301-22050 suitable for Hyundai Accent 1.3 and Sonata.

OE: 27301-22040, 27301-22050

30. 27301-04000 0986221075 2730104000 Ignition coil, suitable for 2011-2015 Hyundai i10, 2011-2014 Kia Morning, and 2011-2015 Kia Picanto.

OE: 27301-04000, 0986221075, 2730104000

31. New ignition coil assembly for the 2014 Hyundai Accent, original part number: 2730103200 27301-03200

OE: 2730103200, 27301-03200

32. Genuine 27301 02600 engine ignition coil for modern ATOS

33. 27301-3CEA0 ignition coil suitable for Hyundai Azera, Sonata, Kia K5, and Optima.

OE: 27301-3CEA0

34. 27301-2B150 27301 2B150 273012B150 2017 Ignition Coil - 2021 Hyundai Sonata Tucson Kia 1.6L

OE: 27301-2B150, 273012B150

35. 27301-2B150 27301 2B150 273012B150 2017 Ignition Coil - 2021 Hyundai Sonata Tucson Kia 1.6L

OE: 27301-2B150, 273012B150

36. 4 OEM 27301-2B140 ignition coils with white dots

OE: 27301-2B140

37. The Hyundai Elantra Tucson, a Kia Ford soul car with an MHJKIA 27300-85010 ignition coil.

OE: 27300-85010

38. 27300-39050 UF432 C1353 ignition coil is suitable for Kia Sedona and Hyundai XG300 XG350.

OE: 27300-39050

39. 27300-03150 Ignition Coil OEM Automotive Parts Car Engine Coil 27300-03150 Suitable for Hyundai Tucson Sonata Equus

OE: 27300-03150

40. Original factory ignition coil 4-pack (27300-2GGA0) suitable for Hyundai Santa Fe, Sonata, Tucson, and Kia Optima.

OE: 27300-2GGA0

41. OEM Ignition Coil for Hyundai Sonata Elantra Kona Forte Kia UF816 27300-2E601

OE: 27300-2E601

42. Ignition Coil ZJ01-18-100 ZJ01-18-100A ZJ0118100A ZJ0118100 AIC-4051 AIC4051 Ignition Coil Mazda 3 BL BK 1.4 1.6 1.4L 1.6L Ignition Coil ZJ01-18-100 ZJ01-18-100A ZJ0118100A ZJ0118100 AIC-4051 AIC4051 I

OE: ZJ01-18-100, ZJ01-18-100A, ZJ0118100A, ZJ0118100, AIC-4051, AIC4051

43. PE20-18-100A For Mazda 3 Sport CX-3 CX-5 2.0L 2.5L 4 pcs OEM NGK Ignition Coil

OE: PE20-18-100A

44. NEW GENUINE/ OEM P51R-18-100 P51R18100 H6T15571 IGNITION COIL for MAZDA

OE: P51R-18-100, P51R18100, H6T15571

45. Ignition Coil For Mazda 5 2.3L 2006-2008 Lfb618100A Auto Replacement Car Accessory Spark Coil 0997000983 K4238 Uf541

OE: LFB618100A, 0997000983

46. Ignition Coil L813-18-100 For Mazda 3 Saloon BK 6 Estate GH Hatchback GG MPV II

OE: L813-18-100

47. Enhance Engine Performance High-Quality High-End Brand Ignition Coil for Models Such as Haima Car OE 483q18100 Tt11d

OE: 483Q18100

48. Ignition Coils 6M8G-12A366 L3G2-18-100A For Mazda 3 6 CX7 MX-5 Miata 2.0 2.3 2.5

OE: 6M8G-12A366, L3G2-18-100A

49. High-performance ignition coil JR3E-12A366-BA for 2018-2021 Ford F150 Mustang 5.0L V8 DOHC Coyote engine.

OE: JR3E-12A366-BA

50. Ignition coil HX7G12A366AA suitable for Ford Fiesta VII, Focus IV, Kuga III 1.5

OE: HX7G12A366AA

51. Ford high-performance ignition coil UF834 HI3z12029c HI3e12029ba

OE: HL3Z12029C, HL3E12029BA

52. Genuine right-side (passenger-side) ignition coil HL3E-12029-AA for Ford truck/van 6.2L engines.

OE: HL3E-12029-AA

53. Ignition coil H6BG12A366AA suitable for Ford Focus IV, Puma, Touareg, and Transit Connect

OE: H6BG12A366AA

54. Fiesta Ka Focus 2.0L car ignition coil GN1G12A366AA GN1G-12A366-AA engine system ignition coil assembly

OE: GN1G12A366AA, GN1G-12A366-AA

55. 305205 ??G0A01 UF713 C872 C1824 099700-213 GN10733 ignition coils suitable for Honda Accord Crosstour, Acura MDX, RLX, and TLX.

OE: 305205, 099700-213, GN10733

56. Ignition coils 30510-P73-A01, 30510-PT2-006, and 30510-P73-A02 are suitable for Honda Accord, Civic,

CR-V, CRX, HR-V, Prelude, and Shuttle.

OE: 30510-P73-A01, 30510-PT2-006, 30510-P73-A02

57. One 90919-02240 ignition coil, suitable for 90919-02265, 90919-T2003, and 90919 02240.

OE: 90919-02240, 90919-02265, 90919-T2003

58. Four OEM-enhanced ignition coils, 90919-02255 UF487, suitable for Toyota RAV4, Camry, and Lexus.

OE: 90919-02255

59. 1992-1993 Toyota Camry/Lexus ES300 ignition coil/igniter 19070-62010 90919-02207

OE: 19070-62010, 90919-02207

60. Two ignition coils for Toyota Supra 3.0L V6 UF386 90919-02205 C975 jto2863

OE: 90919-02205, JTO2863

61. Ignition coil assembly, compatible with Toyota Celica, Corolla, and Tercel 1.5L, 1.6L, 2.0L, and 2.2L engines, can replace UF40 C861 90919-02139

OE: 90919-02139

62. 1PC JTO103 IGNITION COIL T0141 TOYOTA 90919-02163 9091902163 GM 94855502

OE: JTO103, 90919-02163, 9091902163, 94855502

63. Ignition coils 19500-B2040 and 19500-B1010 suitable for Daihatsu vehicles.

OE: 19500-B2040, 19500-B1010

64. 19070-BZ031 19070-BZ030 099700 - Toyota Avanza 2290 ignition coil

OE: 19070-BZ031, 19070-BZ030, 099700

65. Ignition coil 19070-B1011 suitable for Toyota original part number 19070-B1020 Dg2076 Icc-1502

OE: 19070-B1011, 19070-B1020, DG2076, ICC-1502

66. OEM ignition coils for Daihatsu vehicles 19070-97206 1907097206

OE: 19070-97206, 1907097206

67. 19070-97501 19070-97204 Ignition coils, compatible with Daihatsu Hijet LE-S200V

OE: 19070-97501, 19070-97204, LE-S200V

68. UF660 ignition coil for Porsche Cayenne V6 (2008-2018) and Panamera V8/V6 (2010-2016)

69. Ignition coil assembly, 1 piece. Ignition coil 9091902252, suitable for Toyota Corolla, RAV4, Prius. Other models include 90919-02252, 9091902258, 90919C2003, and 90919C2005.

OE: 9091902252, 90919-02252, 9091902258, 90919C2003, 90919C2005

70. Ignition coils: 9091902251, 90919A2002, 90919A2004, 90919A2007

OE: 9091902251, 90919A2002, 90919A2004, 90919A2007

71. Ignition coils: 9091902250, 9091902256, 9091902257, 90919A2003, 90919A2005

OE: 9091902250, 9091902256, 9091902257, 90919A2003, 90919A2005

72. Ignition coil UF-495 UF495 9091902248 9091902260 90919-02260

OE: UF-495, 9091902248, 9091902260, 90919-02260

73. Ignition coils 9091902265 and 90080-19021 suitable for Toyota IQ, ECHO, VITZ, YARIS, and YARIS I.

OE: 9091902265, 90080-19021

74. 9091902239 90919T2002 90919T2006 9008019015 9008019019 9091902262 Toyota Corolla E12 1.8L High-Performance Ignition Coil

OE: 9091902239, 90919T2002, 90919T2006, 9008019015, 9008019019, 9091902262

75. Ignition coils, suitable for Toyota Corolla/Verso (2001-2009), Celica/Coupe (1999-2005), OE numbers:

9091902238, 90919-02238, 88970216, UF314

OE: 9091902238, 90919-02238, 88970216

76. Ignition coils suitable for Toyota Tacoma 2.4L 2.7L L4 UF323 9091902237 C1305 2000-2004

OE: 9091902237

77. Eight ignition coils (9091902249) suitable for Toyota Tundra, Sequoia, Lexus GS430, and LX570 4.3/4.7L engines.

OE: 9091902249, 4.3/4.7L

78. One ignition coil, JTO2245, for Toyota Lexus 90919-02245

OE: JTO2245, 90919-02245

79. 90919-02243 high-performance ignition coil suitable for Toyota Corolla, Camry, RAV4, Matrix, and Scion.

OE: 90919-02243

80. Ignition coil 90919-02235 for 1998-2003 Toyota Nadia SXN10 Vista Ardeo SV50

OE: 90919-02235

81. Ignition coil 90919-02224 is suitable for 1998-1999 Toyota Corolla Prizm 1.8L L4 UF246.

OE: 90919-02224

82. Ignition coil 90919-02221 Toyota Liteace SR40 Chaser SX100 Crown SXS13 3SFE

OE: 90919-02221

83. Ignition coil 90919-02219 for Caldina Carina Corona engine models 7AFE and 4AFE.

OE: 90919-02219

84. Ignition coil OEM# 90919-02215 90080-19012 88921336

OE: 90919-02215, 90080-19012, 88921336

85. Automotive ignition coil 9091902213 UF170, suitable for Toyota Paseo Tercel L4-1.5L (1995, 1996, 1997, 1998, 1999). Contact: 0297007941, 90919-02213, 88921357

OE: 9091902213, L4-1.5L, 0297007941, 90919-02213, 88921357

- 86. High-performance ignition coils for Toyota Sienna and Lexus: UF430 90919-02246 UF506**
OE: 90919-02246
- 87. Ignition coils suitable for Toyota Camry/Corolla/Highlander/RAV4: 90919-02244, 90919-02266, 90080-19023, 90919-02243**
OE: 90919-02244, 90919-02266, 90080-19023, 90919-02243
- 88. Ignition coil assembly 000288233, 1 set (1 piece), compatible with Maserati Ghibli S Q4, Ghibli S, Ghibli, Levante S, Levante, Quattroporte, Quattroporte GTS 3.0T 3.8T/M156/M157**
OE: 000288233, 3.8T/M156/M157
- 89. Ignition coil assembly 000288233, 1 set (1 piece), compatible with Maserati Ghibli S Q4, Ghibli S, Ghibli, Levante S, Levante, Quattroporte, Quattroporte GTS 3.0T 3.8T/M156/M157**
OE: 000288233, 3.8T/M156/M157
- 90. Genuine Ferrari ignition coil, suitable for 599 California, OEM part number 281449**
OE: 281449
- 91. High-performance automotive engine ignition coil parts C2s42673 C2s11480 Xr822478 6r83-12A366-Ba 6r8312A366ba suitable for Jaguar**
OE: C2S42673, C2S11480, XR822478, 6R83-12A366-BA, 6R8312A366BA
- 92. Xw93-12029-Ab Xw93-12028-Ab MB0297008040 Jaguar Vanden Plas Ignition Coil**
OE: XW93-12029-AB, XW93-12028-AB, MB0297008040
- 93. Ignition Heating System 1 ? Ignition Coil 597053 60558152 7648797 134386 UF614 Suitable for Ferrari 348 F355 and Mondial engines.**
OE: 597053, 60558152, 7648797, 134386
- 94. 2018-2019 Jaguar XE ignition coil H4P3-12A366-BB OEM AK2305144**
OE: H4P3-12A366-BB, AK2305144
- 95. Land Rover car parts ignition coil 6r8312A366AA 4744015 4526466 0997001120 Lr016999 Aj83415 Aj810445 Aj87644**
OE: 6R8312A366AA, 4744015, 4526466, 0997001120, LR016999, AJ83415, AJ810445, AJ87644
- 96. Jaguar ignition coil part numbers: 4443006, 6033236, 42533D, 90002444, Lhe1510ab, DMB411, UF-384, UF384, 5c1176**
OE: 4443006, 6033236, 42533D, 90002444, LHE1510AB, DMB411, UF-384, 5C1176
- 97. H30726 ONE 2010-2012 Jaguar XJL XJ XF Engine Ignition Coil 8W9312A366DA**
OE: H30726, 8W9312A366DA
- 98. LR002427 4603135 6H2E12029AA GL1119 Ignition Coil for Land Rover Discovery 3 2005 - 2009 and Discovery 4 2009 - 2018**
OE: LR002427, 4603135, 6H2E12029AA, GL1119
- 99. Ignition Coil Set - Jaguar XK8 / XJ8 / XKR / XJR / XF / S-Type (2W93-12A366-AB)**
OE: 2W93-12A366-AB
- 100. EJG496 Ignition Coil 2W4Z-12029-AB 2W4Z12029AB 2W4Z-12029-AC 2W4Z12029AC**
OE: EJG496, 2W4Z-12029-AB, 2W4Z12029AB, 2W4Z-12029-AC, 2W4Z12029AC
- 101. Jaguar car parts ignition coil 099700-0620 0997000620 1X43-12029-Ab 1X4312029ab**
OE: 099700-0620, 0997000620, 1X43-12029-AB, 1X4312029AB
- 102. Ignition coil. Porsche 996 / 986 / 987 BOXSTER / CAYMAN 1997-11 > 99760210405**
OE: 99760210405
- 103. Ignition coil suitable for Porsche Cayenne 92A 3.6, Macan 95B, and Panamera 970 3.0 (2013-2016 models), OE part numbers: 94660210400, 94660210401, 94660210403, 94660210402**
OE: 94660210400, 94660210401, 94660210403, 94660210402
- 104. Ignition coil 030 905 110 B 030905110B compatible with Volkswagen Voyage 1.0 Flex 2008-**
OE: 030905110B
- 105. OES Ignition Coil 6N0905104 for Volkswagen 6N0 905 104**
OE: 6N0905104
- 106. Suitable for Volkswagen ignition coil 032-905-106b 32905106B 032905106E 032905106 032905106B 32-905-106b**
OE: 032-905-106B, 32905106B, 032905106E, 032905106, 032905106B, 32-905-106B
- 107. Ignition coil EAU414, suitable for 058905105, 058 905 105, 058 905 101, and 058905101.**
OE: EAU414, 058905105, 058905101
- 108. Ignition coil, suitable for models 022 905 100B, 022 905 100E, 022 905 100H, 022 905 100L, 022 905 100P, 022 905 100S, 022 905 100T, 022 905 715, 022 905 715A, 022 905 715B, 022 905 715D, 022 905 715E**
OE: 022905100B
- 109. 95860210100 95560210105 PAB905715 95560210101 95560210102 022905715B Ignition coil, compatible with Audi Q7 and Porsche Cayenne**
OE: 95860210100, 95560210105, PAB905715, 95560210101, 95560210102, 022905715B
- 110. Engine ignition coil, Automotive engine ignition coil, OEM 07K 905 715F 07K905715F, Car engine ignition coil**
OE: 07K905715F
- 111. GN10445 07C905115J Ignition coil, suitable for Audi, Volkswagen, and VW.**
OE: GN10445, 07C905115J
- 112. Genuine ignition coil for Audi A3 A4 A5 Quattro and Volkswagen CC GTI Tiguan, part number 06H905115 06F 905 115H.**
OE: 06H905115

- 113. 06H905115 Genuine Ignition Coil for Audi A3, A4, A5, Quattro, and Volkswagen CC, GTI, Tiguan**
OE: 06H905115
- 114. Ignition coil 06F905115H 06F 905 115H, compatible with Q5**
OE: 06F905115H
- 115. Ignition coil, ignition coil unit 06C905115D**
OE: 06C905115D
- 116. Ignition coils suitable for 06B 905 115, 06B 905 115B, 06B 905 115E, 06B 905 155E, 06B905115, 06B905115B, 06B905115E, 06B905155E, 178-8307, 2505-34912, 36-8043, 84152703, E878, GN10294, IC388, UF-274,**
OE: 06B905115, 06B905115B, 06B905115E, 06B905155E, 178-8307, 2505-34912, 36-8043, 84152703
- 117. MTC 4510 / 06A-905-097 Ignition Coil (06A-905-097 MTC 4510 for Audi/Volkswagen models)**
OE: 06A-905-097
- 118. 05E905110 Ignition Coil**
OE: 05E905110
- 119. 05E905110 Ignition Coil**
OE: 05E905110
- 120. 04C905110 and 04E905110 ignition coils suitable for Audi A3, Volkswagen Jetta, and SEAT Leon**
OE: 04C905110, 04E905110
- 121. Volkswagen ignition coils | 04C905110E, 04C905110H, 04C905110J, 04C905110K**
OE: 04C905110E, 04C905110H, 04C905110J, 04C905110K
- 122. Ignition coils A2769067900 A2769060060 UF777, suitable for Mercedes-Benz C400 C450 E400 GL450 GLC43 GLE43 GLE550e S450 S550e SL400 SL450 3.0T M276 W222 W205 W203 W212 W251 W166**
OE: A2769067900, A2769060060, GLE550E
- 123. Mercedes-Benz CLS C218 ignition coil A2769060260 Original**
OE: A2769060260
- 124. Ignition coils A2749060600 and A2749061400 suitable for Mercedes-Benz A/B/C/E/G/S models**
OE: A2749060600, A2749061400
- 125. Ignition coils A2709060500 A2709060100 UF744 0221604036, 1 set, compatible with Mercedes-Benz GLA200 A180 A200 B180 B200 CLA180 1.6T 2.0T M270 W176 W246 S205 C117**
OE: A2709060500, A2709060100, 0221604036, GLA200, CLA180
- 126. Mercedes-Benz genuine ignition coil A2649061200**
OE: A2649061200
- 127. Ignition coil A2569060100 for Mercedes-Benz E-Class Coupe C238**
OE: A2569060100
- 128. Mercedes-Benz GLC X253 High Voltage Ignition Coil A1779069500 ??- Brand New Original**
OE: A1779069500
- 129. A1721580103 Ignition Coil, compatible with SsangYong Korando Tivoli 1.6L G16DF 2.0L G20 2012-**
OE: A1721580103
- 130. Ignition coil 1611583203 (A1611583203) is suitable for SsangYong, Actyon, Kailong, Korando, E23 Sport, and gasoline engines.**
OE: 1611583203, A1611583203
- 131. Ignition coil A1611583103**
OE: A1611583103
- 132. New Bosch ignition coils for Mercedes-Benz: 0986221058 2729060060**
OE: 0986221058, 2729060060
- 133. Electronic ignition coil, replacement part number: 0001587803 / A0001587803 / 0221503035**
OE: 0001587803, A0001587803, 0221503035
- 134. Ignition coil A0001587203 0001587203 000-158-72-03 A000-158-72-03**
OE: A0001587203, 0001587203, 000-158-72-03, A000-158-72-03
- 135. A0001502880 ignition coil suitable for Mercedes-Benz W203 W210 C208 A208 W210 R170**
OE: A0001502880
- 136. High-performance ignition coil kit (4-piece set) for Mercedes-Benz C250 SLK250 C200 C180 C230 E200 E260 SLK200 1.8T L4 M271 C203 S204 W204 W212 models: A0001502580 A0001502980 UF555 UF658**
OE: SLK250, SLK200, A0001502580, A0001502980
- 137. New type of ignition coil 0001500780 0001501380 A0001500780 A0001501380**
OE: 0001500780, 0001501380, A0001500780, A0001501380
- 138. Mercedes-Benz M-Class W163 ML 230 0001500280 0001587003 Ignition Coil**
OE: 0001500280, 0001587003
- 139. Ignition coil 224332935R A2829060000 1.3TCE Renault Dacia Mercedes-Benz**
OE: 224332935R, A2829060000
- 140. OEM Eldor ignition coil 12138657273 for BMW 2001-2015**
OE: 12138657273
- 141. Ignition coil: 12138647463, 12137619385, 12138678438, 12138643360, 0986221124, 8678438, 8647463, 12138615991**
OE: 12138647463, 12137619385, 12138678438, 12138643360, 0986221124, 8678438, 8647463, 12138615991
- 142. Bosch ignition coil 0 221 504 800**

143. Ignition coils 12137838388 7838388 12137841754, compatible with BMW E90 E92 E93 LCI M3 S65 UF-597.

Automotive parts.

OE: 12137838388, 7838388, 12137841754, UF-597

144. Ignition coil assembly 12137835108, compatible with BMW VEHICLE-ES.

OE: 12137835108

145. OEM ignition coils for Bosch BMW 325i, 328i, 335, 525, 528, 530, 535 X3, X5: 0221504470

OE: 0221504470

146. Ignition coil 12137594936 is suitable for (325I, 325XI, 330I, 330XI, 525I, 525XI, 530I, 530XI, Z4).

OE: 12137594936

147. BMW genuine ignition coil 504 470 12137594937

OE: 12137594937

148. Ignition coils for BMW E81, E87, E88, E82, E90, E91, E92, E93, and E60 models. One ignition coil is 12137594935.

OE: 12137594935

149. High-quality ignition coils (12137575010, 12137550012, 597091) suitable for DS/Peugeot 408/MINI/BMW/N13B16A 1.6T engines.

OE: 12137575010, 12137550012, 597091, 408/MINI/BMW/N13B16A

150. Six ignition coil sets (12131712219) for BMW Z4 E85 2.0, 2.2, 2.5, and 3.0 models from 2002 to 2008.

OE: 12131712219

151. 12131703227 Temporary Coil Spark Plug Connector, Automotive Compatible with BMW 12139067830 0221504029

OE: 12131703227, 12139067830, 0221504029