

Threaded Quick Links and Delta Connectors

A quick link is a screw closed connector that joins chain, rope and hardware without a tool. Honke makes the standard oval body from 3.5 mm to 14 mm and the delta shape from 3.5 mm to 12 mm in stainless and steel.

- 2 items in this range
- Screw gate that opens and closes by hand without tools
- Oval body for in line chain work and delta body for three way junctions
- Stainless steel for wet and coastal work, steel where price leads
- 3.5 mm to 14 mm covers most chain and rope sizes in the retail channel

Contact

WhatsApp +86 181 4895 2022 Email denny@honkehardware.com.cn

201, Building 2, Headquarters Center, Panyu Energy Saving Technology Park, No.555 Panyu Avenue North, Panyu District, Guangzhou, China

Plant: Longyan City, Fujian Province, China | 4,500 sq m floor area | 100 staff

Quick Links Specifications



S7350

QUICK LINK

Rigging Hardware curt threaded quick link Stainless steel chain connecting link 3.5mm-14mm

MATERIAL	Stainless steel, Steel Iron
SIZE	3.5mm-14mm
FINISH	Polishing, plating, etc
DESIGN	OEM & ODM



S7360

DELTA SHAPE QUICK LINK

Delta shaped stainless steel chain quick connector link 3.5mm-12mm

MATERIAL	Stainless steel, Steel Iron
SIZE	3.5mm-12mm
FINISH	Polishing, plating, etc
DESIGN	OEM & ODM

Frequently Asked Questions

When should I use a delta quick link instead of an oval one

The delta shape has a wide flat base, so it holds three legs apart and keeps them from riding on top of each other. Use the oval body for a simple in line join.

Should the gate be tightened with a tool

Hand tight is normal. Overtightening with pliers deforms the thread and makes the link very hard to reopen later.

Are quick links load rated

Rating depends on size, material and market. Tell us the standard your buyer works to and we will confirm what we can supply for that item.

What sizes are available

The standard quick link runs 3.5 mm to 14 mm and the delta version runs 3.5 mm to 12 mm.

Can they be used in salt water

Choose the stainless steel version for salt exposure and rinse the thread with fresh water so the gate keeps turning.